Approved For Release 2004/02/14 - C/A-RDP78B05703A000200040022-6

NPIC/D-41/70 9 FEB 1970

HENORANDUM FOI	: Deputy Director of Security (PTGOS)	
SUBJECT:	Safety -	25X1
REPERENCE:	Fire and Safety Survey - dated	25X1
· · · · · · · · · · · · · · · · · · ·	30 June through 10 July 1969,	25X1
	Security Officer, APIC	25X1
	occurry different many	
l. I hav	e read the Fire and Safety Survey - espection of the building in July 1969 by	25X1 25X1
	I commend those two officers for the	25/1
of their repor	of their inspection and the clarity and usefulness	
2. NPIC	s response to that Survey is attached. In summary,	
wo have correc	ted some situations, are proceeding to correct	
for us to solv	e seeking ways to cope with a few which are difficult e. As you know, we have some difficult safety	
problems pecul of and in this	iar to the nature of our business and to conditions	
	_	
NPIC component	dition, I have met with the chiefs of the principal s to review our in-house safety inspection and	
maintenance pr	ocedures. I have issued instructions to initiate onitor) the following procedures:	
	Safety items will be logged on a daily basis by	
our Secur	ity Branch Duty Officers as part of their daily	
Security/	Safety tours of The resulting	25X1
TIBELLINGS	will be known as the Daily Safety Log.	
b.	Each major component in will designate	25X1
remedial	Safety Officer responsible for the initiation of actions surfaced in the Daily Safety Log.	
c.	Chief, Support Services Division will monitor the	
completio	n of remedial actions undertaken under 3b, above.	

Declass Review by

25X1

25X1

25X1	SUBJECT: Safety -	
	d. A new NPIC Notice covering revised NPIC safety practices will be issued.	
	4. Incidentally, I am still perplexed by the recommendations to install automatic water sprinkler systems in all areas of the building without regard to the nature, replaceability or cost of the equipment housed in each area. My confusion on this subject is compounded by the seemingly uneven application of this requirement throughout the Agency, particularly in areas housing highly technical equipment, the conflicting advice of suppliers and consultants, and the wide range of solutions, or non-solutions, applied by commercial firms throughout the country.	
	5. There are areas in that obviously slould return to the sprinkler system and we are prepared to take these actions. In other locations we are skeptical that water is the best solution to our problem keeping in mind a concurrent management responsibility to stay operational. Therefore, we are developing an NPIC view on each of the areas in question and we will be seeking from you a better spread of available options. You will be hearing more from us on this subject.	25X1
	6. Again, my thanks to I request that another thorough inspection be made in 1970 by those officers or officers of like caliber from your Office.	25X1
	Executive Director National Photographic Interpretation Center	25X1
	Distribution: Orig & 1 - Addressee 1 - NPIC/TSSG/SSD 1 - NPIC/TSSG/SSD/SB 2 - NPIC/ODIR 2 - NPIC/TSSG	
25X1	NPIC/TSSG: (6 February 70)	